

**NOTE: Before performing any maintenance and troubleshooting, unplug the system.**

If the size or appearance of the surface boil has decreased from initial installation, perform one or more of the following:

**Air Filter Cleaning / Replacement**

- Unscrew the filter from the compressor; pop the top off by pushing in the tabs on the side. Remove the foam filter, clean with soapy water, dry completely and replace.

**Check Diffusers for Material Build Up or Damage**

- The diffusers located on the AirPod may have been damaged (wildlife and fishing hooks are most common) or blocked by material build up (after a long period of inactivity). Remove the AirPod to inspect that the membranes are clear with no rips or holes. Clean or replace as necessary.

**Piston Rebuild Kit**

- Rebuild kits are available by contacting Aqua Control or your distributor. Normally, a rebuild should not be required for up to three years of normal operation.